



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
March 14, 2011

Reviewed: *RL*

Mine Name: Ticaboo Stockpile Removal
Operator Name: Ucolo Exploration Corporation

Permit number: S/017/0050
Inspection Date: December 1,
2010
Time: About 2:00 PM

Inspector(s): Paul Baker and Tom Munson
Other Participants: None
Mine Status: Inactive

Weather: Mostly clear, 40s

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds, Permit Fees	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

The area had had a substantial rainstorm, and we wanted to check whether there had been damage to the berm around the stockpile.

Inspection Summary:

The Division holds a reclamation surety of \$10,000.00 in the form of a certificate of deposit. The permit fee is up to date.

3. Protection of Drainages / Erosion Control

There has been a fair amount of erosion off the stockpile. It appeared the berm had breached in one location but that it had been fixed.

Conclusions and Recommendations:

I recommend that the ditch on the inside of the berm be cleaned out so it is ready for runoff from the next storm.

Inspector's Signature *RLB*

PBB:eb

cc: sfivecoat@blm.gov, wtokes@utah.gov

Loree Gregg

O:\M017-Garfield\S0170050-TicabooStockpileRemoval\inspections\ins-12012010.doc



Photo 1. It appears the berm was fixed.



Photo 4



Photo 2. Photos 2 through 4 show some erosion off the stockpile.



Photo 3